





Sand Pits - 1996 & 2004 West CR 112, Midland, TX




EPA Region 6
Superfund
GIS Support
5/21/12



-  Former Texas Plastics Facility Property
-  Pit extent from 1982 aerial photo.

Sources: 1996 image from Google Earth; 2004 image and boundaries from Banks Environmental Data.






1996 image with 1982 boundaries.

Sand Pits - 1996 West CR 112, Midland, TX

- Former Texas Plastics Facility Property
- Pit extent from 1982 aerial photo.

The sand pit boundary from the 1982 aerial is shown over a 1996 image from Google Earth. Sources: Google Earth, Banks Environmental Data.



EPA Region 6
Superfund
GIS Support
5/21/12



LOCKHEED MARTIN



